

Coordinates:
 perche $\langle 45.435212$
 26.061165
 Rompra $\langle 45.435533$
 26.061312

LE6E404:

 - patchet

 P.P - platform priming

7 - drum tractor

Б - болячо

UNITATEA DE PRODUCȚIE VII

1 - drum tractor
2 - borma

34A
 8MO-1BR-1FA
 40-0.9-3

35A
 4MO-3FA-2BR-1DM
 50-0.9-3

36A
 4MO-3FA-2BR-1DM
 50-0.9-3

37A
 7MO-2FA-1BR
 45-0.9-3

38A
 4MO-3FA-2BR-1DM
 50-0.9-3

39A
 4MO-3FA-2BR-1DM
 50-0.9-3

40A
 4MO-3FA-2BR-1DM
 50-0.9-3

41A
 4MO-3FA-2BR-1DM
 50-0.9-3

42A
 4MO-3FA-2BR-1DM
 50-0.9-3

43A
 4MO-3FA-2BR-1DM
 50-0.9-3

44A
 4MO-3FA-2BR-1DM
 50-0.9-3

45A
 4MO-3FA-2BR-1DM
 50-0.9-3

46A
 4MO-3FA-2BR-1DM
 50-0.9-3

47A
 4MO-3FA-2BR-1DM
 50-0.9-3

48A
 4MO-3FA-2BR-1DM
 50-0.9-3

49A
 4MO-3FA-2BR-1DM
 50-0.9-3

50A
 4MO-3FA-2BR-1DM
 50-0.9-3

51A
 4MO-3FA-2BR-1DM
 50-0.9-3

52A
 4MO-3FA-2BR-1DM
 50-0.9-3

53A
 4MO-3FA-2BR-1DM
 50-0.9-3

54A
 4MO-3FA-2BR-1DM
 50-0.9-3

55A
 4MO-3FA-2BR-1DM
 50-0.9-3

56A
 4MO-3FA-2BR-1DM
 50-0.9-3

57A
 4MO-3FA-2BR-1DM
 50-0.9-3

58A
 4MO-3FA-2BR-1DM
 50-0.9-3

59A
 4MO-3FA-2BR-1DM
 50-0.9-3

60A
 4MO-3FA-2BR-1DM
 50-0.9-3

61A
 4MO-3FA-2BR-1DM
 50-0.9-3

62A
 4MO-3FA-2BR-1DM
 50-0.9-3

63A
 4MO-3FA-2BR-1DM
 50-0.9-3

64A
 4MO-3FA-2BR-1DM
 50-0.9-3

65A
 4MO-3FA-2BR-1DM
 50-0.9-3

66A
 4MO-3FA-2BR-1DM
 50-0.9-3

67A
 4MO-3FA-2BR-1DM
 50-0.9-3

68A
 4MO-3FA-2BR-1DM
 50-0.9-3

69A
 4MO-3FA-2BR-1DM
 50-0.9-3

70A
 4MO-3FA-2BR-1DM
 50-0.9-3

71A
 4MO-3FA-2BR-1DM
 50-0.9-3

72A
 4MO-3FA-2BR-1DM
 50-0.9-3

73A
 4MO-3FA-2BR-1DM
 50-0.9-3

74A
 4MO-3FA-2BR-1DM
 50-0.9-3

75A
 4MO-3FA-2BR-1DM
 50-0.9-3

76A
 4MO-3FA-2BR-1DM
 50-0.9-3

77A
 4MO-3FA-2BR-1DM
 50-0.9-3

78A
 4MO-3FA-2BR-1DM
 50-0.9-3

79A
 4MO-3FA-2BR-1DM
 50-0.9-3

80A
 4MO-3FA-2BR-1DM
 50-0.9-3

81A
 4MO-3FA-2BR-1DM
 50-0.9-3

82A
 4MO-3FA-2BR-1DM
 50-0.9-3

83A
 4MO-3FA-2BR-1DM
 50-0.9-3

84A
 4MO-3FA-2BR-1DM
 50-0.9-3

85A
 4MO-3FA-2BR-1DM
 50-0.9-3

86A
 4MO-3FA-2BR-1DM
 50-0.9-3

87A
 4MO-3FA-2BR-1DM
 50-0.9-3

88A
 4MO-3FA-2BR-1DM
 50-0.9-3

89A
 4MO-3FA-2BR-1DM
 50-0.9-3

90A
 4MO-3FA-2BR-1DM
 50-0.9-3

91A
 4MO-3FA-2BR-1DM
 50-0.9-3

92A
 4MO-3FA-2BR-1DM
 50-0.9-3

93A
 4MO-3FA-2BR-1DM
 50-0.9-3

94A
 4MO-3FA-2BR-1DM
 50-0.9-3

95A
 4MO-3FA-2BR-1DM
 50-0.9-3

96A
 4MO-3FA-2BR-1DM
 50-0.9-3

97A
 4MO-3FA-2BR-1DM
 50-0.9-3

98A
 4MO-3FA-2BR-1DM
 50-0.9-3

99A
 4MO-3FA-2BR-1DM
 50-0.9-3

100A
 4MO-3FA-2BR-1DM
 50-0.9-3

101A
 4MO-3FA-2BR-1DM
 50-0.9-3

102A
 4MO-3FA-2BR-1DM
 50-0.9-3

103A
 4MO-3FA-2BR-1DM
 50-0.9-3

104A
 4MO-3FA-2BR-1DM
 50-0.9-3

105A
 4MO-3FA-2BR-1DM
 50-0.9-3

106A
 4MO-3FA-2BR-1DM
 50-0.9-3

107A
 4MO-3FA-2BR-1DM
 50-0.9-3

108A
 4MO-3FA-2BR-1DM
 50-0.9-3

109A
 4MO-3FA-2BR-1DM
 50-0.9-3

110A
 4MO-3FA-2BR-1DM
 50-0.9-3

111A
 4MO-3FA-2BR-1DM
 50-0.9-3

112A
 4MO-3FA-2BR-1DM
 50-0.9-3

113A
 4MO-3FA-2BR-1DM
 50-0.9-3

114A
 4MO-3FA-2BR-1DM
 50-0.9-3

115A
 4MO-3FA-2BR-1DM
 50-0.9-3

116A
 4MO-3FA-2BR-1DM
 50-0.9-3

117A
 4MO-3FA-2BR-1DM
 50-0.9-3

118A
 4MO-3FA-2BR-1DM
 50-0.9-3

119A
 4MO-3FA-2BR-1DM
 50-0.9-3

120A
 4MO-3FA-2BR-1DM
 50-0.9-3


121A
 4MO-3FA-2BR-1DM
 50-0.9-3

122A
 4MO-3FA-2BR-1DM
 50-0.9-3

123A
 4MO-3FA-2BR-1DM
 50-0.9-3

124A
 4MO-3FA-2BR-1DM
 50-0.9-3

125A
 4MO-3FA-2BR-1DM
 50-0.9-3



teh.
C3 - 202

VĂLE 750